

Photos of renewal works in progress



Photo 1: LTA staff overseeing the safe delivery of the new trains at Jurong Port.



Photo 2: Testing works for the new track circuit system to ensure stability of the system.



Photo 3: The new power supply system features new Voltage Limiting Devices, which isolates power faults to prevent line-wide disruptions.



Photo 4: The software of new signalling system was tested at the signalling simulation facility before deployment on the main track.